Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EDR ID Number

CU485 TRANSFORMER VAULT VS5747 NY Spills S103939032 SW WEST 24TH ST/SURF AVE N/A

1/2-1 BROOKLYN, NY

0.756 mi.

3991 ft. Site 4 of 7 in cluster CU

 Relative:
 SPILLS:

 Higher
 Name:
 TRANSFORMER VAULT VS5747

 Actual:
 Address:
 WEST 24TH ST/SURF AVE

3 ft. City,State,Zip: BROOKLYN, NY

Spill Number/Closed Date: 9903682 / 2000-05-18

9903682 Facility ID: Facility Type: ER DER Facility ID: 127109 Site ID: 149419 DEC Region: 2 Spill Cause: Unknown Spill Class: C3 2401 SWIS: Spill Date: 1999-06-30 Investigator: CAENGELH Referred To: Not reported 1999-06-30 Reported to Dept: CID: 252

Water Affected: Not reported Spill Source: Commercial/Industrial

Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0

Date Entered In Computer: 1999-06-30
Spill Record Last Update: 2000-06-06
Spiller Name: UNKNOWN
Spiller Company: Unknown
Spiller Address: UNKNOWN

Spiller Company: 999

Contact Name: FRANK MASSERIA

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

ENGELHARDT con ed e2mis notes: approx 1 oz unknown oil on 1800 gallons of water. He pressure tested transf. Tranf pcb record is 12

ppm. <1ppm, cleanup complete, incident is closed. "

Remarks: "CLEANUP PENDING SAMPLE RESULTS."

All Materials:

 Site ID:
 149419

 Operable Unit ID:
 1078247

 Operable Unit:
 01

 Material ID:
 303591

 Material Code:
 0066A

Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00

Oxygenate: Not reported